



BEVERAGE-AIR

LEADERS IN INNOVATION & RELIABILITY SINCE 1944

Warranty Guidelines

Maximum Standard Labor Allowance for Repair of Equipment

➤ **One-Half Hour of Labor for diagnosis of unit problem.**

➤ **One-Hour Labor for Replacement of (and test of unit) :**

Temperature Control	Digital Thermometer	Vent port repair	Transformer	Repair Slide Lid (DW/GF)
Condensate Element	Defrost Timer	Door Locks	Ballast	Door switch
Door/Drawer Roller Bearings	Start components	Door gaskets	Fan motors and blades	

➤ **Two-Hours of Labor for Replacement of (and test of unit):**

Defrost Limit Switch	Fan Delay Therm-O-Disc Defrost Heating Elements	Hi-Limit Therm-O-Disc
----------------------	----------------------------------------------------	--------------------------

➤ **Two and One-Half Hours of Labor for Replacement of (& test of unit):**

Face Heaters	Defrost Heating Elements	CPR Valve	Lift-Out System
--------------	--------------------------	-----------	-----------------

➤ **Three to Four Hours Labor, depending on model, for Replacement of (and test of unit):**

Compressor	Condenser Coil	Suction/Cap Tube Assy.	Ref. Restrictions
Condenser Unit	Evaporator Coil	Thermostatic Expansion Val	Low Pressure Control

Following are limitations that pertain to Beverage-Air Corporation's limited warranty for parts & labor. Other limitations may apply. Please refer to factory warranty document:

- Product loss is **NOT** covered under factory warranty.
- Warranty covers repairs due to manufacturing defects and/or component failures.
- Equipment that has been subjected to damage, neglect, misuse, misapplication, etc. is not covered by factory warranty.
- Overtime rates will be covered by factory warranty at the service company's straight time rate. The difference between straight time rate and overtime rate will be between the end user and the servicer. Example: the unit owner is responsible for paying the difference in rates between straight time and overtime rate if requesting service outside of normal business hours.
- **Calibrations, adjustments, lubrications, cleanings, etc. are **NOT** warranty repairs.
- Evacuate & recharge system: \$25.00 max refrigerant recovery allowance (Total of \$50 max. Recovery, evacuate, torch, & brazing).
- Allowances for new Refrigerant are \$16.00/lb for R134a and \$20.00/lb for R404A.
- Two-hour maximum allowance for travel -includes round trip. Travel in excess should be referred to a sub-agent. Travel beyond these warranty guidelines must have prior approval from Beverage-Air Corp.
- All parts returned to Beverage-Air must have a Return Goods Authorization Number (**RG#**) clearly marked on the outside of the packaging of the goods returning in order to be accepted and credited.
- Installation, removal and re-installation of units, and special installation situations are not covered under warranty. This includes, but is not limited to, built-in units, units under counters, behind bars, remote applications, etc.
- Repairs exceeding Beverage-Air Corp. Warranty Guidelines must have a detailed description of special circumstances for consideration of coverage.